



TSB-100 ♦ Tray Former

- ◆ All Mechanical Simplicity
- ◆ Up To 3300 Trays Per Hour
- ◆ No Air Required
- ◆ Compact Size
- ◆ Portable



W.E.

Plemons



MACHINERY SERVICES, INC.

Geared to the World



P.O. Box 787 ♦ 13479 E. Industrial Dr. ♦ Parlier, California 93648 ♦ (559) 646 - 6630 ♦ Fax (559) 646 - 9630

Visit our Website @ www.weplemons.com



Tray Styles





#1 Tray W/ Top Flaps





#2 Single Top Flap Tray





#3 Tray W/ Split Minor Flaps





#4 One Piece Full Telescope





#5 Leak Proof Tray





#6 Two Piece Full Telescope



#7 Diagonal Corner Tray




#8 Diagonal Corner Tray
W/ Locking Top Flaps





#9 Laminated Tray



Tray Styles





#10 Collapsible Tray





#11 Corner Flange Seal Tray





#12 Diagonal Corner
Corner Flange Seal Tray





#13 Tapered Tray






#14 Mini Corner Flange Seal Tray





#15 Roll-Over Locking Tray



#16 Rounded Top Tray




#17 Tray W/ HSC Cover




#18 Tray W/ Locking Top Flap

Machine Specifications


ITEM	STANDARD BASE	WIDE BASE
WIDTH	63 1/2"	75 1/2"
LENGTH	50"	50"
HEIGHT	78 - 92"	78 - 92"
WEIGHT	2100 LBS	2400 LBS
APPROX. SPEED RANGE	0 - 60 PER MIN	0 - 60 PER MIN
ELECTRICAL STANDARD	240 V 3 PHASE - 60 Hz	
ELECTRICAL OPTIONS	208, 480 AND 600 VOLT 3 PHASE - 60 Hz Single Phase Available.	



Standard Base



Wide Base



Kwik Change

PMS STANDARD FEATURES

- Vacuum Feed Attachment
(1 HP vacuum motor (1/3 more vacuum))
- Powder Coated Frame
- Time Delay Drive
- Down Stream Control Wiring
- Quick Change Bottom Stops
- One Piece Frame Uprights (no splices)
- One Piece Trees (no splices)
- Bearings in lower frame have seals for wash down
- "No Lube" Linear Bearings on Vacuum Feed Block
- "Lexan" Guard at Rear of Machine
- Spring Loaded Compression Rollers
- Large Capacity Glue Pots
(Complete melt down - 30 min.)
- Safety Interlocks on all Guards and Lower Frame Side Panels
- Nema 4x Electrical Enclosure

OPTIONAL EQUIPMENT

- Large Casters (Includes Mounting Pads)
- Extended Body Hopper (8" Longer)
- Missing Panel Sensors
- Low Level Hopper Sensors
- Kwik Change "Crank Adjustable" Bottom Stops
- Kwik Change Top Compression
- Down Stream Photo Eye w/ 20ft S.O. Cord
- Box Counter
- Nordson ProBlue Glue System
- Corner Flange Seal Attachment
- Roll-Over Locking Attachment
- Automatic Lidding Attachment



W.E.

Plemons

MACHINERY SERVICES, INC.